

ARCADIS GERAGHTY & MILLER



Mr. Brad Bradley
United States Environmental Protection Agency, SR-6J
77 West Jackson Blvd.
Chicago, IL 60604

ARCADIS Geraghty & Miller, Inc.
35 East Wacker Drive
Suite 1000
Chicago
Illinois 60601
Tel 312 263 6703
Fax 312 263 7897

Subject:
CONRAIL Site
Elkhart, Indiana

ENVIRONMENTAL

Dear Mr. Bradley:


Attached please find a list of EPA monitoring wells that we gauged during our last site visit (April 1999). Inadvertently, the locks on most of these wells were replaced. Enclosed please find keys to the locks we installed during our last site visit (April 1999). If you have any questions or comments please contact the undersigned.

Chicago,
21 May 1999

Contact:
Jim Hertel

Sincerely,
ARCADIS Geraghty & Miller, Inc.

Extension:
312.263.6703


Jim Hertel, P.G.
Geologist

Copies:
Project file

EPA Region 5 Records Ctr.



258778

Table 2 Monitor Well Gauging Data - Select USEPA Wells
CONRAIL Railyard, Elkhart, Indiana - April 1999

Well ID	Depth to Water	Total Depth of Well	Comments
MW-13S	9.66	11.85	OK
MW-13D	9.77	79	OK
MW-24	9.29	9.85	Filled to 9.85' w/gravel, needs to be replaced.
MW-25	8.38	19.44	OK
MW-28S	7.54	17.47	OK
MW-28I	7.92	52.25	OK
MW-29S	11.19	42.65	OK
MW-29I	10.90	>100.0	OK
MW-30S	8.22	17.87	OK
MW-30I	8.82	52.42	OK
MW-30D	8.73	>100.0	OK, well labeled in field.
MW-30BR	8.69	>100.0	OK, well labeled in field.
MW-31S	9.98	17.28	OK
MW-31I	10.39	54.54	OK
MW-33S	6.48	15.94	Riser needs to be lowered, gripper plug replaced.
MW-33I	6.70	45.12	OK
MW-34	8.26	49.75	OK
MW-36I	7.14	54.75	Needs gripper plug.
MW-47	6.81	37.85	OK
MW-49D	6.43	15.58	Needs manhole/concrete pad.
MW-49BR	6.40	83.27	Needs manhole/concrete pad.

Monitor well ids sources:

- 1) Ecology and Environment, Inc., June 1992, Volatile Organic Chemical Results
For Phase II Groundwater Samples.
- 2) Ecology and Environment, Inc., April 1993, Remedial Investigation/
Feasibility Study for the CONRAIL Site Elkhart, Indiana, Alternatives
Array Document, Figure 2-3.